onBalance

Case History #oB_0005M

onBalance Case History #oB-00005M

The (homeowner name) pool on (homeowner address) in Tracy California was built by Aqua Pool and Spa, and plastered by Burkett Pool Plastering. According to the records of Aqua Pools and Spas, the pool was built and plastered in April of 1998, and turned over to a service company, Aqua Chlor, who started the service on 4/20/98. On 4/21/98 the service company documented that the pool surface was "mottled" and "faded."

This pool was involved in legal activity between the owner of Aqua Pools and Spas, and Aqua Chlor. To date, the pool has yet to be replastered. However, the litigation is now completed. To summarize, the litigation involved a suit instigated by Aqua Chlor (plaintiff) on multiple counts, including breach of contract, trademark infringement, and slander issues. The slander issue included the contention that the builder and/or plasterer were blaming the poor appearance of pool surfaces on the quality of service provided by Aqua Chlor. Aqua Chlor's position was that the statements constituted slander, especially in light of their contention that the damage to the pools was actually a result of construction defects.

Two years into the lawsuit, the owner of Aqua Pools and Spas counter-sued, contending that they were due damages based upon the damage they felt Aqua Chlor caused to a list of specific pools.

Aqua Chlor engaged onBalance as expert witnesses in the actions, and Aqua Pools and Spas engaged Rob Burkett and Greg Garrett as expert witnesses.

During the course of the litigation, this pool was core sampled four times:

- Two cores taken by Greg Garrett and submitted to RJ Lee Group (Dr. Boyd Clark) for analysis
- Two cores taken by onBalance and submitted to RJ Lee Group (Niels Thalow) for analysis
- One core taken by onBalance and used as a court exhibit
- One core taken by Rob Burkett for use as a court exhibit, but which was not entered into evidence due to failure to follow rules of disclosure

Also, the builder was required as part of the litigation to provide a list of plaster components. That listing declared that the pool plaster was composed of cement, aggregate, water, calcium chloride, and Davis dye. It was also brought out in deposition that the plastering crew used wet tools or wet finishing techniques, as well as engaging in hard troweling.

The resolution of the lawsuit and counter-suit were as follows:

- The counter-suit was dismissed on summary judgement, meaning that the court dismissed the Aqua Pools and Spas allegations without hearing evidence, determining that the legal action was without merit.
- The original suit was decided by a jury in favor of the plaintiff (Aqua Chlor), and monetary damages were awarded. Additionally, legal fees were paid by the defendant (i.e., the owner of Aqua Pools and Spas and/or his insurance company).

It is important to note that neither the judge nor the jury actually made a ruling as to specifically who was responsible for the condition of the pool plaster surfaces. The verdict rendered was a general verdict on all causes of action. However, the general verdict was for the plaintiff (Aqua Chlor), and against Richard

Townsend, owner of Aqua Pools and Spas. No defendant in this case was awarded any monetary judgement, legal fees or costs.

Hundreds of pages of testimony, both in deposition and in open court, were generated by this lawsuit, as well as the generation of several lab analyses. The gist of the evidence presented is that:

- The primary characteristic of the surface problems in this pool can be characterized as excessive porosity and the leaching of calcium (Clark)
- The surface did not display the characteristic evidence of acid etching (Thalow)
- The pattern of the leaching may have been associated with the finishing process, with local areas of higher water:cement being more susceptible to leaching (Thalow)
- There was a high concentration of chloride... and it is known that this may influence the color of concrete surfaces (Thalow)
- There is a known incompatibility between calcium chloride and Davis color dye, which can result in blotching and discoloration (Davis)
- There is a known correlation between the use of wet finishing tools and surface paling (Davis)
- There is a known correlation between over-troweling and surface discoloration (Davis)
- There is a specific causal chain of events evidenced in this pool, which includes the use of incompatible admixtures, prohibited finishing practices, and an overall disregard for professional workmanship practices which, in this pool, led to the severe discoloration seen on the pool surface (onBalance)
- It is permissible to violate manufacturers recommendations if the contractor believes they do not apply (Garrett & Burkett)
- Dr. Boyd Clark's statements mean something other that what Dr. Clark says they mean (Garrett & Burkett)
- Plaster is, indeed, composed of portland cement, aggregate, and water, but it is not really a version of concrete, so accepted concrete practices, rules, and guidelines such as those from the Portland Cement Association and the American Concrete Institute do not apply (Garrett & Burkett)
- In spite of the lack of any hard evidence, and in spite of hard evidence to the contrary, this pool was discolored by aggressive water chemistry (Garrett & Burkett)
- Attachment A Written report by onBalance
- Attachment B Written report by Dr. Clark
- Attachment C Written report by Mr. Thalow
- Attachment D Scanned image of the Davis Color Chart (note injunctions against wet finishing and overworking, and the statement that the use of calcium chloride is the only known incompatibility, which causes blotching and discoloration)
- Attachment E Photograph of a Davis Powder Color tint package (note injunctions against wet finishing, overworking, and use of calcium chloride)
- Attachment F Photograph of a Davis Liquid Color tint package (note injunctions against wet finishing, overworking, and use of calcium chloride)

onBalance

Swimming Pool Chemistry and Plaster Consulting

Mr. Jerry Wallace General Manager, Aqua Chlor

Re: onBalance Project oB-00005M

Mr. Wallace:

You engaged onBalance to diagnose the cause(s) for discolorations on the surface of the swimming pool plaster located at [homeowner's address] in Tracy California, at the residence of [homeowner's name]. The onBalance partners visited the pool on a number of occasions, including two visits to obtain core samples of the pool for analysis. The following is a summary of the observations and results of the analysis.

Methods

Visual/Tactile

The pool was inspected when filled with water and when drained.

The grey plaster pool exhibits a spotted discoloration pattern, and the pattern coincides with fan patterns of discoloration, smeared material at surface, smeared plaster up onto the grout, driplines, etc. (see attached photo and microphotographs).

At these inspections, it was noted that the plaster surface was predominantly very smooth to the touch and to visual analysis (with the exception of the smeared areas).

Optical Photography

Photographs were taken of the pool. The photographs document the spotting, the distribution of the spots, driplines, fan patterning, etc.

Document Review

onBalance performed a review of start-up and weekly chemical maintenance records maintained for this pool. The chemical ranges were maintained within accepted industry standards, and the documentation does not show any incidences of aggressive water conditions.

Core Analysis

Photography – The pool was core sampled, and the cores were photographed both in situ and in the lab. *Photomicrography* – The surface of a core sample was photographed at 40X magnification, with care taken to document the level of surface cement paste erosion as evidenced by the exposure of aggregate (sand) at surface. The surface was found to be smooth, and did not display characteristics of aggressive chemical attack.

Chloride analysis – A sample of the plaster was analyzed for chloride content using ASTM Standard Method C1152 (Standard Test Method for Acid-Soluble Chloride in Mortar and Concrete) and a Hach Quantab titrator variation of ASTM Standard Method C114.19 (Standard Test Methods for Chemical Analysis

of Hydraulic Cement – Chloride). The chloride content was found to be 428 ppm, which calculates to 2.4% calcium chloride dihydrate by weight to the cement in standard swimming pool plaster.

Laboratory Analysis

Review of RJ Lee Analysis by Dr. Boyd Clark – We have reviewed the analysis of the pool's plaster by Dr. Clark, which you provided to us (RJ Lee Project #MAH912505). Dr. Clark's report is observational in nature, rather than specifying causation, and states that he is not determining the mechanisms for the artifacts he observes. He finds that the outstanding characteristic of the phenomenon is excess porosity. He also notes the reconstruction of components (calcium and silica phases) into separate microstructures, rather that the combined microstructure that one would normally expect. He notes a degree of carbonation and ionic movement which is facilitated by the fact that the material (plaster) was submerged in fluid (pool water), which makes these things happen at a faster speed than if the cementitious material had been kept relatively dry (such as driveways, sidewalks, and other cement-based cores he is hired to analyze). He notes that the pH of hydration was lower than that of saturated Ca(OH)2. This means that the ponding fluid (pool water) was at a pH lower than 13. In the supplemental report, Dr. Clark reinforces his conclusion that the primary problem is one of porosity. He rules out abnormal calcium depletion.

Commission of Analysis by Niels Thalow of RJ Lee – onBalance cored the pool and sent the two cores (along with two samples from another pool we analyzed for you) to Mr. Niels Thalow of RJ Lee Group for analysis. The two cores from this pool are identified in the report (RJ Lee Group Project #MAH112353) as M1 and M2. Mr. Thalow is an internationally recognized expert in the diagnosis of the various types of aggressive attacks on cement-based surfaces. His finding was that there was no evidence of aggressive attack, and hypothesized that the patterning (fan-shaped sweeps) may be due to the finishing process, which included a technique which left areas or spots of high surface water:cement ratios. He also notes the addition of high concentrations of calcium chloride – an admixture known to cause porosity and colormottling.

Observations

- The presence of calcium chloride is associated with discoloration in cementitious products. Industryaccepted documentation from the Portland Cement Association, the American Concrete Institute, and other authorities indicate that even low levels of calcium chloride (<2%) will cause discoloration. The accepted standard is to not exceed 2% dihydrate to the weight of the cement. However, there is also a provision in the standard that all admixtures must be compatible. Calcium chloride and color plaster admixtures are not compatible. Davis Color was reportedly used in this pool. Attached is a copy of Davis' color chart, stating that there is a known incompatibility with calcium chloride. Also attached are copies of the Davis color powder and liquid packaging which includes the statement of incompatibility. Tests of the this pool plaster show levels of calcium chloride which exceed the industry-accepted maximum even for white plaster. Since there should be no chloride at all in this plaster, exceeding 2% is a particularly serious failure on the part of the plastering contractor.
- The microphotographs of the this plaster were compared by onBalance with photographs of other plaster standards (at the same magnification) which had been subjected to known degrees of aggressive chemical attack. There was no indication of an aggressive attack on this surface.
- There are indications that the plaster surface was finished with wet tools, or that water was applied to the surface during finishing. This is a poor finishing practice which is prohibited by ACI and PCA. Davis Color also indicates on the attached color chart and on the packaging that water should not be used in finishing. The striped walls of the pool, along with chatter marks, is an indication that

water was applied to the finished surface and that the finished surface was then hard troweled after the time such troweling could be safely accomplished.

This plaster coating is thin, as seen in the photographs, which also may have played a role in the discoloration problems.

Conclusion

The pool has not undergone an aggressive chemical attack. None of the accepted hallmarks of aggressive attack (such as surface cement paste dissolution and etching of the surface-exposed aggregate) are evident. This is consistent with the chemical history documentation provided onBalance and with the analysis undertaken by onBalance.

Many factors are usually associated with spot discolorations, including excess calcium chloride, wet finishing, and overworking the surface. All of these factors appear to have been contributory to the problems seen in this pool.

Sincerely, Partner – onBalance Consulting



oB-00005M a – Pattern on wall



oB-00005M b – Pattern on wall with trowel



oB-00005M c – Pattern on wall closeup

onBalance Case History oB-0005M



oB-00005M d - Cores



oB-00005M e – A Core in situ

oB-00005M f – Smeared material

onBalance Case History oB-00005M



oB-00005M g – Chatter marks

RJ Lee Group, Inc. 350 Hachberg Road Manroeville, PA 15146 Tel: (724) 325-1776

Fax: (724) 733-1799

The Materials Characterization Specialists

March 6, 2000

Mr. Greg Garrett Applied Materials Technologies, Inc. P.O. Box 7842 Chandler, AZ 85246-7842

RE: RJ Lee Group Project # MAH912505

Dear Mr. Garrett,

Cross sections of two core samples were examined by scanning electron microscopy (SEM). The samples were identified as Core #1 (small spots) and Core #2 (large spots).

Both core samples were a black colored top surface (the surface in direct contact with any swimming pool water) with white "spots" and were coated with an epoxy over the surface, as received by RJ Lee Group. The cores were sectioned through the top surface and then the cross-section was polished using diamond grit abrades.

The results from our manual SEM analyses follow.

Summary of results, Core #1 (small spots):



- Aggregate particles are observed, generally, directly below each spot.
 ✓ Four small spots sectioned, three of the four have an aggregate directly beneath the spot.
- Spots consist of two-phase regions, calcium-rich and silicon-rich.
 - Affected regions appear as silicon-rich "grains" in a calcium-rich matrix.
 - Two phase region is indicative of carbonation and/or matrix reconstruction.
 - Silicon-rich grains are "relics" of former cement grains.

Spot regions are more porous than the surrounding paste matrix.

Affected spot regions are approximately 50 microns in depth.

Page 1 of 3

Monroeville, PA · San Leandro, CA · Washington, DC · Richland, WA

しんちれきますい

- Fine voids/pores are evident in affected regions.
- Silicon-rich regions are more porous than the surrounding calcium-rich matrix.
- Two thin, calcium-rich layers are evident in both the unaffected and affected regions.
 - Two distinct layers are evident, one indicative of crystal precipitation from solution.
 - ✓ Layers are 5 to 10 microns in total thickness.
 - Layers are indicative of carbonation.
- Cracking due to shrinkage is apparent in the unaffected interior paste.
 - Crack pattern indicative of shrinkage during curing is observed.

Summary of results, Core #2 (large spots):

- · Affected spot regions cover most of the surface.
 - Two-phase region is apparent along most of the top surface.
- Spotted region again consists of two-phase regions, calcium-rich and siliconrich.
 - Again, affected regions appear as silicon-rich "grains" in a calciumrich matrix. Although some spots have regions where the silicon-rich region is not just grains.
 - Two phase region is indicative of carbonation and/or matrix reconstruction.
 - Silicon-rich grains are "relics" of former cement grains.
- Spot regions are more porous than the surrounding paste matrix.
 - Affected spot regions are between 0.1 to 0.2 millimeters in depth.
 - Fine voids/pores and cracks are evident in affected regions.
 - Silicon-rich regions are more porous than the surrounding calcium-rich matrix.
- Two thin, calcium-rich layers are evident in both the unaffected and affected regions.
 - Two distinct layers are evident, one indicative of crystal precipitation from solution.
 - Layers are 5 to 10 microns in total thickness.
 - Layers are indicative of carbonation.

Page 2 of 3

Conclusions:

- The discoloration observed is due to an increased porosity in the affected spot. This increased porosity is due to both the increased number of fine pores/voids and higher porosity in the silicon-rich phase.
- The increased porosity in the affected regions is due to a reconstruction of the paste matrix. This reconstruction of the paste matrix can only be achieved " through the movement of material by a solution, most probably the swimming pool fluid, through the already hydrated cement paste. The overall appearance of the reconstructed paste is indicative of a water/solution driven dissolution/carbonation reaction.
- The observed two-phase microstructure, near the top surface, indicates a
 process other than normal curing hydration of the former cement grains. The
 decalcification and hydration of former cement grains indicates hydration has
 occurred at a pH level lower than that of paste saturated with Ca(OH).
- The mechanism for this dissolution/carbonation reaction is undetermined at this time. The reaction appears to initiates within paste between an aggregate particle and the top surface and proceeds around the aggregate particle, into the surrounding matrix.
- The thin layers of carbonation along the top surface are both due to movement
 of material, calcium, either from the cement paste matrix and/or from the
 swimming pool fluid. The mechanism for this carbonation reaction(s) is also
 undetermined at this time.

Suggested Additional Analyses:

- Optically thin cross-sections to establish that the thin surface layers are indeed carbonation and whether there are any differences between the two materials.
- Stereo-optical analysis examining the size of aggregate particles versus the spot size. Analysis is intended to determine whether there is a relationship between aggregate size and spot size.

Sincerely,

Boyd Chirk

Boyd Cfirk Senior Materials Scientist RJ Lee Group, Inc.

Page 3 of 3

-











Sample No. 0811960 Client ID Large Spots



Page 6 of 10





Sample No. 0811960 Client ID Large Spots



Interior Region of Sample Cracking Indicative of Shrinkage

Page 9 of 10

Sample No. 0811960 Client ID Large Spots



Interior Region of Sample Cracking Indicative of Shrinkage

Page 10 of 10









Sample No. 0811959 Client ID Small Spots



Low Magnification of An Unaffected Region along Top Surface

Page 5 of 10







Sample No. 0811959 Client ID Small Spots



Page 9 of 10

Sample No. 0811959 Client ID Small Spots



Page 10 of 10





RJ Lee Group, Inc.

H350 Hochberg Road Monroeville, PA 15146 Tel: (724) 325-1776 Fax: (724) 733-1799

April 25, 2000

Mr. Greg Garrett Applied Materials Technologies, Inc. P.O. Box 7842 Chandler, AZ 85246-7842

RE: RJ Lee Group Project # MAH912505; Supplemental Report

Dear Mr. Garrett,

Cross sections of two core samples were examined by scanning electron microscopy (SEM). The samples were identified as Core #1 (small spots) and Core #2 (large spots).

The results from the analyses of these two cores were presented in a report dated March 6, 2000. In our subsequent discussions you requested we answer four additional questions:

- Is the pigment defective?
- Is there a depletion of calcium along the top surface?
- When did the dissolution/carbonation reaction occur?
- Can we give a range at which the pH of the solution would cause the dissolution/carbonation reaction occur?

To answer the first two questions additional SEM analyses were required. The pigment content and relationship to the spotted regions was examined by backscattered electron microscopy (BSE). X-ray mapping was used to evaluate the calcium content along "unaffected regions" at the top surface.

BSE images of pigment particles are shown as attached figures. Pigment particles were observed throughout the sample. Pigment particles were observed in the spotted regions, but were more prevalent in the unaffected paste.

X-ray maps were taken from the top surface within unaffected paste regions and are shown in the attached figures. No discernable difference is observed in calcium content as a function of depth.



Monroeville, PA + San Leandro, CA + Washington, DC + Richland, WA

Summary of results:

- Lat. Souther Card and Card
- Barium sulfate and iron-rich pigment particles observed.
 - ✓ Barium sulfate more easily observed.
 - ✓ More barium sulfate observed in affected regions than iron.
 - Iron-rich particles are detected in affected region, but more prevalent
 - in unaffected region.
- · X-ray maps do not show discernable difference in calcium content.
 - ✓ X-ray maps taken along top surface, in unaffected paste regions.
 - No enrichment or depletion is observed.

Conclusions:

- The discoloration observed is mostly due to an increased porosity in the affected spot. I have conferred with Niels Thaulow concerning the iron-rich particles and he indicates the overall number of particles is far less than would be expected from his past experience; both in the affected or unaffected regions. Further SEM analysis is recommended of the starting pigment material.
- No depletion of the calcium content near the surface is observed, as shown by X-ray mapping.
- Our previous analyses indicate that the spotting occurs after plaster hydration. This is best exemplified by relics of former cement grains that show unusual hydration (i.e. a high silicon to calcium ratio).
- Further testing is required to fully determine the range of pH (in the pool solution) that can cause the two-phase microstructure observed in the first report (dated 3/6/00). I have conferred with Niels Thaulow, and neither he nor I can relate these types of effects to previous projects.

Sincerely,

a. Chife

Boyd Clark Senior Materials Scientist RJ Lee Group, Inc.
Sample No. 0811960 Client ID Large Spots



BSE Low Magnification Image Interface Between Affected Region and Unaffected Paste Interior

Page 1 of 11

Sample No. 0811960 Client ID Large Spots



1. 4.

Sample No. 0811960 Client ID Large Spots



Sample No. 0811959 Client ID Small Spots



. e

Sample No. 0811959 Client ID Small Spots



BSE Low Magnification Unaffected Region

Page 5 of 11

Sample No. 0811959 Client ID Small Spots



Sample No. 0811959 Client ID Small Spots



BSE Low Magnification Unaffected Region

Page 7 of 11

Sample No. 0811959 Client ID Small Spots



Sample No. 0811959 Client ID Small Spots



RJ LeeGroup, Inc.

350 Hochberg Road Monroeville, PA 15146 Tel: (724) 325-1776 Fax: (724) 733-1799 The Materials Characterization Specialists

February 18, 2002

Mr. Que Hales Pool Chlor 3116E Pennsylvania Street Tucson, AZ 85714

RE: Petrographic Examination of Concrete Project No. MAH112353

Dear Mr. Hales:

Enclosed is a summary of the results from the examination of two concrete samples by scanning electron microscopy (SEM) and acid soluble chloride analysis. Four concrete samples were received at RJ Lee Group's laboratory on December 12, 2001. The samples were identified as follows:

RJ Lee Group	Client	Type of Test
Sample No.	Sample ID,	Performed
0815911	ES1	Not analyzed
0815912	ES2	SEM and acid soluble chloride analysis
0815913	M1	Not analyzed
0815914	M2	SEM and acid soluble chloride analysis

The concrete samples submitted for petrographic analysis were first examined visually. Samples ES1 (0815911) and ES2 (0815912) were chunks of mortar having two layers. The bottom mortar layers were gray in color, top layers were dark-gray in color and approximately 54" in thick. White areas were observed on the top, almost completely covering the surface. Samples M1 (0815913) and M2 (0815914) were cores of approximately 254" diameter. Similarly, these cores consisted of two layers. The top layer was approximately 52" thick. White spots were observed on the top surface. The samples were photographed in its as-received condition. The depth of carbonation was measured after slicing and application of phenolphthalein. A section obtained from the top of the core was analyzed by SEM. Small amounts of powdered samples from the top layers were used for acid soluble chloride analysis according to ASTM C1152/1152M-92. The analysis results are summarized in a table.

SEM Sample Preparation

Vertical cross sections of sample ES2 and M2 were cut from the samples after sections cut for carbonation test. The sections were polished using 163 through 30 µm grit abrasives. The sections were dried, and vacuum impregnated using a low viscosity epoxy resin that contained a fluorescent dye. The excess epoxy was removed using metallographic abrasive papers. Care was taken not to grind into the sample. The impregnated samples were then polished using consecutively finer silicon carbide grit slurries (600 to 1000 grit) on a glass plate. Polishing was performed starting

> Monroeville, PA • San Leandro, CA • Washington, DC • Pasco, WA www.rjlg.com

Page 2 of 3

with the use of 9 µm diamond paste and final polishing to 1/4 µm diamond paste on cloth. The polished surface was then coated with a thin layer of carbon by evaporative deposition.

SEM Analysis

The prepared section was analyzed using an SEM operated in the backscattered electron (BSE) imaging mode, coupled with energy dispersive spectroscopy (EDS). The top layers of the samples were analyzed comparing white verses dark areas. BSE images of representative features are attached in the Appendix B.

Sample No. 0815912 (ES2)

- · Depth of carbonation at the top of the sample was about 1 mm.
- Crushed dolomite was used as fine aggregate.
- · Decalcification of C-S-H was observed below the carbonation layer.
- Depletion of calcium hydroxide was observed in this zone.
- AFt deposits were observed below the decalcification zone.
- Increased porosity was observed in the decalcified zone.
- The carbonation zone at the top surface was not uniform.
- Below the decalcified zone cracking of the paste was observed, which extended 2-3 mm.
- The paste was not altered below this zone.
- · Calcium hydroxide was present in this zone.
- · The composition of the C-S-H was normal.
- Patches of Cl-rich AFm and C-S-H were observed.
- · Estimated water to cementitious ratio was 0.45 in the unaltered zone.

Sample No. 0815914 (M2)

White area

- · Depth of carbonation at the top of the sample was about 1 mm.
- Crushed dolomite was used as fine aggregate.
- · Decalcification of C-S-H was observed below the carbonation layer.
- Magnesium silicate formation was observed.
- Depletion of calcium hydroxide was observed in this zone.
- · AFt deposits were observed below the decalcification zone.
- Increased porosity was observed in the decalcified zone.
- The carbonation zone at the top surface was not uniform.
- Below the decalcified zone cracking of the paste was observed, which extended 3-4 mm.
- The paste was not altered below this zone.
- · Calcium hydroxide was present in this zone.
- · The composition of the C-S-H was normal.
- · Patches of Cl-rich AFm and C-S-H were observed.

Dark area

- Depth of carbonation at the top of the sample was about 1 mm.
- · Minor decalcification of <1 mm thickness was observed below the carbonation zone.
- · Magnesium silicate formation was observed.
- · The paste was unaltered below this zone.

Page 3 of 3

- Cracking of the paste was not visible.
- Patches of Cl-rich AFm and C-S-H were observed.
- Estimated water to cementitious ratio was 0.45 in the unaltered zone.

Summary

Petrographic analysis of the concrete samples shows white area on the surface. The paste of the white areas shows carbonation and decalcification of the C-S-H. Increased porosity was observed in these areas. Below this decalcified zone, deposits of ettringite and cracking were observed. This altered zone extends up to maximum 5 mm. Angular, fine aggregates were exposed at the surface due to loss of material from the surface. The exposed dolomite aggregate did not show evidence of acid etching. The white areas seem to form due to local leaching of cement paste creating porous, decalcified areas. The pattern of the leached areas may have been determined by the finishing process, with local areas of higher w/c being more susceptible to leaching of calcium ions.

Bulk analysis of mortar indicates high concentration of chloride present in the samples. The chloride-containing compounds were distributed all over the cement paste, except the decalcified zone. This indicates that chloride was added to the mortar mix. It is known that addition of calcium chloride accelerators may influence the color of the concrete surface.

The results are submitted pursuant to RJ Lee group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which the results are used or interpreted. The samples for this project will be stored for a period of 60 days.

If you have any questions or if you want us to do any further investigations, please call me at 724-325-1776.

Sincerely,

martin

Niels Thaulow Director of Construction Materials

Attachments







Sample No. 0815913 - M1



-

Sample No. 0815913 - M1



 \sim

53



























AFt deposit(s)





18

28.8 69

11854



EPH Fillow Elesson (Fs)-Heip) (2000 - 111 - 12 u - 0 - 112 - 12 u - 0 - 12 - 12 u

Dense paste



RP041A.lyo

Page 3 of 12

(c) 1997-00 RJ Lee Group, Inc.

EX14817.11

58.62 m







001.5914010.72F

Cl-rich AFt/AFm











Magnesium enrichment

RP04L4.3yo	Page 9 of 12	(c) 1997-00 RJ Lee Group, Inc.

Magnesium enrichment

881 5914834,721

38.EX SPO

ia.

Y (mm) 16.813

144

Y (mm) 16.788

16 m




MAH112353 - Sample No. 0815914 - M2







RJ LeeGroup, Inc.

Acid Soluble Chloride Analysis

Project No: MAH112353

RJ Lee Sample No.	Client Core Id.	Chloride Concentration (wt.%)
615912	ES2	0.38
815914	M2	0.32

Note: Chloride percent is by mass of concrete





You have also asked me to clarify a general point made in my past reports. In past reports I have used the terminology "...water driven reconstruction of the hydrated cement paste" in describing changes observed in the hydrated paste microstructure. This terminology only describes the way in which ionic species (calcium, chloride, salfate, etc...) can be moved within the paste microstructure.

Differences in solubility of the various paste components will allow one species to move more or less freely through the paste porosity (as examples calcium chloride and calcium carbonate will have very different solubilities in water of pH 7). Once the local solution chemistry changes (on the microscopic level) the ions in solution may precipitate as another compound. Thus, to conclude that the water (solution) is "aggressive" to the paste misinterprets the microstructural changes, the problem could very well be that the paste has components that are ill suited for the environment (calcium chloride as an example is soluble over a wide pH range).

I believe that the present study Pool Chlor and RJ Lee Group are undertaking, evaluating a number of plaster failures in comparison to industry prepared standards, will give us the insight to understand these paste reconstruction phenomena.

Boyd A. Clark, Ph.D. Senior Materials Scientist

MIX-IN COLORS FOR CONCRETE

Uses: Davis Colors are used in cast-in-place, slab-on-grade, precast, tili-up and ornamental concrete; shotcrete, mortar, concrete masonry units, pavers, retaining wall units and rooffile. They can also be used to color cast stone, plaster, stucco and other cement-based construction materials. Designed for mix-in use only, they should not be sprinkled or dusted onto the concrete surface.

Ingredients: Pure, concentrated pigments made of high-quality metal oxides recycled from iron or refined from the earth and specially processed for mixing into concrete. Davis Colors comply with ASTM C979 Pigments for Integrally Colonal Concrete. They are lightfast, alkali-resistant, weather-resistant, durable and long-lasting like concrete. Davis Colors are available in a wide spectrum of standard colors and can be custom formulated to match design requirements. * Unlike other Davis Colors, Sapra-Instant* black #8084 is a specially treated carbon black. Carbon black is the highest in tint strength and the most economical, but can fade if concrete is not sealed against water penetration. Sealing and periodic re-scaling can minimize this effect.

Packaging: Concrete suppliers use our Mix-Ready® disintegrating bags or Chameleon® bulk handling system. Mix-Reads* bags are tossed into the mix without opening or pouring. They disintegrate under mixing action, releasing pigments to disperse uniformly leaving no bags to litter the environment. The Chameleon¹⁹ is a computer-controlled automatic bulk-color dosing system.

Installation: Integrally colored concrete is installed the same way as high quality uncolored concrete. Choose a color on the inside of this color card and specify it by name, color number and dose rate. Create a custom color by varying the amount of color added to the mix. Confirm desired color with a hilly-cured job-site test panel. Typical dose rates range from 1/2 to 7 lbs, per 94 lbs, of cement content and should never excord 10% of centent content. Gement content includes portland centent, fly ash, slica firme, lime and other cementitious materials but does not include aggregate or sand. Davis Colors have been used successfully in a wide variety of mix designs and are compatible with commercially available admistrates. The only known incompatibility is with calcium chloride set accelerator which causes blotching and discoloration. * Supra-Instant® black #8084 reduces or negates the effect of air-entraining admistures.

Finishes: Paving and foors can be finished with pattern-stamped, broomed, troweled, exposed aggregate, sak-fnished, sand-blasted, or many other visually appending textures. Cast-in-place, precast and tik-up structures can be textured with sand-blasting, bushharmering, grinding, polishing, special forms or form liners. The combinations and possibilities are endless. Here are just a few



Curing & Sealing: W-1000 Clear* is a non-clouding, spray-on cure and scaler that meets or exceeds ASTM C309 standards and is specially formulated for colored concrete and exposed aggregate finishes. Other curing methods, such as water curing or plastic sheets cause discoloration. Color Seal²⁴ is an optional, thin-film scaler that's tisted to match the shades on this Color Selector. When applied over colored concrete or the W-1000 Clearss, it provides a more uniform appearance.

Quality Tips: For best results; materials, curing, weather conditions and workmanship should be uniform throughout a project. Quality starts with the concrete mix; use a low water-content, high-performance mix design. When planning a project, budget for craftsmanship.

Consumer Advice: Contractors are independently owned and operated without affiliation to Davis Colors. Choose a licensed and qualified contractor who provides written information and example projects you can see before you buy. Check the yellow pages, ask your local ready mix or building material dealer or visit www.concreteconnection.com to find contractors who specialize in colored concrete.

Specify Davis: Choose a color from this color selector and specify it by name, color number and dose rate. Add color call-out to plan documents or specifications. For complete architectural and guide spec information, visit our web site, refer to our architectural binder, call, fax or write. Our guide specifications can be found in SweetSource", Spec-Data", ARCAD Spec-Disk" or at www.daviscolars.com/lech. For samples or additional information contact:



Tel: 800-356-4848 Fax: 323-269-1053 www.daviscolors.com

Mixing Guide:

the the same pigment-to-cement ratio, type and brand of centers and aggregates throughout project. Changes in centent and aggregate color affect final color.

Keep slump less fran 57 (12.5 cm) and water content consistent. High water content causes concrote to appear pale or "faded". If higher shamp is required, use a water reducing admixture instead of added water

Calcture Chloride sei ancelerator causes discoloration, Do not use with color.

Specify air content of 5% to 7% for improved workability and long term durability in freeze/how climates

Schedule loads for consistent mix times. Deliver and discharge in less due 1-1/2 hours. Clean never thoroughly heween color charge-overs.

Confirm color number and weight in Mix-Ready* hog (or combination of bags) is the same required by raix design.

Wet mixer with 1/2 to 2/5 total hatch water. 'Biss In-Mix-Beady* hags and mix of charging speed for at least one minute. Add cement, aggregate and remaining batch water. Continue mixing at charging speed for at least 5 minutes (7 minutes for pea-genvel mines).

Notice: In mixes with small aggregate or batches with short mixing distation, Mix-Ready⁶ hags may not completely disintegrate. In sand-blasted or exposed aggregate thisfles, use small hag sizes (15 fbs. maximum) or open bag and pour color normally.

The Chameleon¹⁹ is a computer-controlled color dosing. system for Ready Mix operators exclusively from Davis. It improves color accuracy and availability. Chameleon74 dose rates differ from the rates on front of this card. For more information, go to www.daviscolors.com/chandeou.

Contractor's Guide:

Prepare a well-drained subgrade. Add a 2 to 3 inch (50 to 75 mm) layer of sand, gravel or crushed stone. Uniformly compact the subgrade and moisten events, leaving no publies, standing water, ice, frost, or muddy areas.

If super harrier is used, overlap sheen and tape over holes in hurrier. Place a S' (75mm) layer of granular self-draining compactible fill over the hurrier to minimize shrinkage cracking

Position forms for uniform slab thickness. Follow American Concrete Institute standards for reinforcement and joint placement to control crucking.

Allow apple time and manpower for placement and flaish work. Finish evenly and with care.

Begin trowellag after bleed water evaporates. Late or hard troweling and edging causes "horns" or dark spots.

Water added at job-site to initier or purips will cause color to pale. Keep additions to a minimum and consistent among loads. Don't wet flatishing tools or broats or sprinkle water on the surface.

Do not spitable pigment or cement onto the surface.

Rotary, dry-broom, pattern stamped or rough finishes usually cure more even colored than smooth-troweled linishes

Uneven curing-uneven dring-uneven color. Care colored concrete with Davis W-1000 Clear" cure and seal. (info at: www.datiscolors.com/literature/pdf/W-1000.pdf) Do not use plastic sheets, water curing or curing products which discolor. Wood and other objects left on curring concrete cause discoloration.

Efforencence is a white powdery substance that appears on concrete surfaces. A result of water evaporation, it is more noticeable on colored surfaces making them look faded or lighter in color when not cleaned off. Proper curing and protection against water prostration reduces tendency for efforescence to occur. Bemore with detergent or mild-acid cleaners formulated to remove efflorescence. Follow cleaner instructions and test in a small area to make sure cleaner will not each or discolor the surface. Wear rubber glores and eye protection.

Because the could/ons of use and application of our products are beyond our control, DANS COLORS MARES NO INMPRANTY OF MERCHARTABLITY OR FITNEES FOR ANY PARTICULAR PREPOSE and expressly discipline liability for consequential or incidental damages whether lased on warranty or negligence. Buyer's sole remedy shall be reliand of color parchase price from paint of parchase. C2012 Solis Calors all rights reserved. We Healty" and Supra-Instant" are registered trademarks of Savin Calors. Printed in U.S.A. 1212

Davis Oplans" me color "Admittmes" made of metal or minieral buildes, ditting recyclicd from iron or retired from the earth that are lightlast, limeptoot and permanent. They want orm conclust into the stud dreams are made of

The Davis Colors, card shows a spectrum of concrete colors. Castern color studen are made by rary-ting the amount of color added to the mix. Mix-Ready, colone are dissigned for mix-in Lee only, not "dust-on" use. Every tatch of Davis Colors is tonted to verify 4

exceleds industry redunitionants for consistancy. Color of concrete may differ them color card or samples and is influenced by the base color of regneral, mix water both

tent, finishing methods and curing conditions Please mad the Davis Colors" Card, Hew To Brochure or contact Davis Colors for Jics on using this product.

Mix-Realty* bagenite made of special paper which modely get soggy and disintegrate under mining action subscript oder open in the mover to dispetzer uniformly. Color sum ding is clean and environmential wester minimized.

CONLECTER

transcriede (CASS 1309-37-1 or 1317-51 9 or 512 M-09 Thr combination) Silicon Droxide-Amelphotia ICA6 7(01-08-9) 1

Keep-dry in a cool place away from sources of as a b opon flame? Barturistic and Breaking

HAZARDS

Cantact a Doctor II accidentally ingestied, This product is nen-hazardous and non-toxic. Protect operant inhalation, where eve protection and avoid contract with sidiupr claming. Claim-up with stop and water. Rater MISDS for camplete handling information

HANDLING

Knep unused argument in closed container. Protect against noduci can stati and spillage and accidental contra create duto a mass.

Recycle in process waterwaver possible. Verify currant red uistory statum witherfalls waske agoncy on the EPA builden disagong in autocoded trouble. Product parties EPA 1990 ntonia (40 CFR part 23 - 300460) ARORIGA TOPP

100

Select a color by number and mix rate from the copy office. Contintil the color number and weight in this bed for

- combination olyags) is the same required by the por-Lies the lowest number of bags required for the back. Mix limition this bag = 1 per cubic yand meters
- Wet giver drum with approximately Ter to 2.3 fittal beigh water. Toss in Mix-Ready bags and mix at charging speed for at least one minute
- Add certeen and appropriate and remaining batch mater Continue mixing at charging upsed fount teast 5 minutes (7 minutes for pee gravel mixes)

.

Keep skimp less man 5" (12.5 cm) and water

- content consistent among balohije. Do not use with Caldum Chloride set acquierator
- Schedule loads for consistent mix times. Olden enter
- thoroughly to prevent opion carry-over

- Graides compact and moisten subgrade motoughly
- Micro extra time for placement and hrear way S Later - All eventy and with care Do not over-trawel. Retery, dry-broam or rough finishes usually dure more even-colored than smooth
- finishes usony care that wet broom. travelled finishes, Do not wet broom. Weter, added at job site to mixer of putter will cause agent to "pale" keep additions to a barn minimum and
- consistent among loads

- Gurw colored controlle with Davie W-1050 Clean Cure re-Seal of Color Seal II in a matching color. Do not deel plasific sheats, water coling or other cureo
- products which can disorter. Wood contact car) stant, train condrete.

Package and codients have not been tested for compatibility with every admixture or in all nits designs Confirm comparisity with the concrete miniand check a test pour butoro tinalizion mix design. Field theok min characteristics/throughout bour(b).



Made in U.S.A. by Dovin Colors Los Angeles DA 90023 - (323//269-7311 Beltsville, MD 20705 - (30#) 210-3400 #

5/1985 F.D. Davis Co. All rights fourward Mis Readings a registered tridemark of EB. Drave OS



stains and discoloration.

- Do not use in concrete with Calcium Chloride set-accelerator.
- Keep mix time consistent. Clean empty mixer thoroughly.

JOBSITE TIPS

- Grade, compact and moisten subgrade thoroughly and evenly.
- Allow <u>extra</u> time for placement and finish work. Finish evenly and with care.
- Do not over-trowel or start troweling late. Do not wet-broom.
- A broom, rotary or textured finish will be more even-colored. A hard, dark, slipperysmooth finish is made by extended troweling.

or or 19

ST

1

1.1